

Longshore Safety Tip

SAFETY ON STEEL PIPE

August 2008



- ✓ Pipe is protected with a coating of oil creating a very slippery walking surface.
- ✓ Always be aware of your footing.

- ✓ Check slings for wear and tear/damage (PCMSC Rules 258 & 1035)
- ✓ Keep loads level.
- ✓ Avoid turning your back on the load.



- ✓ Do not climb on top of a load to unhook slings.
- ✓ Make sure the load is level in the bunks before unhooking slings.
- ✓ Don't try to stop rolling pipe.



ILWU/PMA
PACIFIC COAST MARINE SAFETY COMMITTEE
DEDICATED TO SAFETY



SAFETY ON STEEL PIPE



- ✓ **When moving pipe always drive in reverse.**
- ✓ **If you drive forward and have to stop you could lose the load.**

- ✓ **When cold decking - avoid high piling pipe.**
- ✓ **Keep piles level.**
- ✓ **Place and secure wedges on the front and rear of the pile.**



- ✓ **Always wedge stickers.**
- ✓ **Keep piles straight.**
- ✓ **Keep stickers in a vertical line.**
- ✓ **Keep walkways between the stacks unobstructed.**



Use extreme caution when working on steel operations.



ILWU/PMA
PACIFIC COAST MARINE SAFETY COMMITTEE
DEDICATED TO SAFETY

