Longshore Safety Tip

Auto Vessel Safety Awareness

Working an Auto Vessel can pose a different set of hazards to Longshore workers.

It is important to remember the following safety rules..

Watch out for:

- 1. Pedestrians
- 2. Low Overheads
- 3. Vehicle Traffic
- 4. Tripping Hazards
- <mark>5. Wet/Slippery Dec</mark>ks & Ramps



Use the designated walkways





Obey all Posted
Speed Limits,
Driving &
Traffic
Instructions





ILWU/PMA
PACIFIC COAST MARINE SAFETY COMMITTEE
DEDICATED TO SAFETY



Auto Vessel Safety Awareness

Wear your PPE!

High Visibility Safety Vests must be worn at all times.


Lashers

Wear Knee Pads, Gloves, and Coveralls

Slide Lashing on Deck

Practice Good Housekeeping

Watch Out for Lashing Points



<u>Drivers</u>

Pay Attention to Low Overheads

Watch for protrusions like trailer hitches & Lashing Bolts

Watch for and Follow Spotter's Directions

Use Caution around Tripping Hazards



- Pay attention to pedestrians and vehicle traffic.
- Obey all posted speed limits, and maintain a safe speed at all times.
- Follow all designated routes.
- Always ride completely inside the shuttle van when returning to the ship
- Wear your Seatbelt