
Longshore Safety Tip

SEMI TRACTOR TIP OVER Semi Tractors can tip over and major injury or death can result.



Tip overs may occur IF:

- 1. You are in the jack knifed position when backing, as the stability footprint of the unit is reduced.
- 2. Your 5th wheel is all the way up, as the center of gravity is raised and stability is reduced.
- 3. You make a sudden acceleration or jerky motion while backing.
- 4. You are driving too fast while cornering.



Semi Tractor Driver Safety

The key to staying alive and reducing the

chances of injury or death during a roll

over is wearing your seat belt.

Avoid tipping over by:

1. Using the S-curve backing procedure and avoid using the jack knife method if possible.

S-Turn backing Visible Side

- 2. Keep your 5th wheel as low as possible, without hitting or grounding the landing legs. This will lower the center of gravity. (This may require cranking up the landing gear.)
- 3. Avoid sudden acceleration, jerky motions, or sudden stopping while backing. Always back in slowly and smoothly.
- 4. Whenever possible, avoid blind side backing. If you must use this procedure check that the area is clear of hazards and pedestrians.
- 5. Obey all speed and traffic regulations. PCMSC Rule 904.
- 6. Inspect all vehicles prior to use and report any defects. PCMSC Rule 901.

One of the most important pieces of "PPE" is... **YOUR SEAT BELT**

Wear it at all times—PCMSC Rule 921